

Sliddele TIG STOR 201 SR17

incl. Standard, Gaslinse, Stubby, Jumbo, Glasklar og Glasdyse



Brænderkrop:

80300196A – 70mm SR17
 80300197A – 70mm SR17FX
 80300198A – 90mm SR17FX
 705.0033 - 60mm SR17
 703.0009 SR17FX
 712.1020 - 65mm SRT17
 712.1030 - 65mm SRT17FX



Elektrodehætte:

80300200B – kort
 80301902B – mellem
 80300201B - lang



O-ring for elektrodehætte:

80300223B



Isolator:

80300189A

svejse madsen

Bjarne Risbjerg Madsen ApS

☎ 98 23 14 36

Oversigtsliste.: 50141063OS

Sliddele TIG 201 SR17

Standard dele

Keramisk gasdyse L47,5mm:



80340001B – 6,4mm – gr.4
 80340002B – 8,0mm – gr.5
 80340003B – 9,5mm – gr.6
 80340004B – 11,0mm – gr.7
 80340005B – 12,7mm – gr.8
 80340006B – 15,7mm – gr.10
 80340007B – 19,0mm – gr.12

Elektrodeholder TIG:



80310004B – 1,0mm.
 80310000B – 1,6mm.
 80310001B – 2,4mm.
 80310002B – 3,2mm.
 80310003B – 4,0mm.

Spændbøsning SKRÅ:



80330101BS – 1,6mm
 80330102BS – 2,4mm
 80330103BS – 3,2mm

Spændbøsning:



80330100B – 1,0mm
 80330101B – 1,6mm
 80330102B – 2,4mm
 80330103B – 3,2mm
 80330104B – 4,0mm

Keramisk gasdyse L76mm:



80340170A – Gr. 5L – 10N49L – 8,0mm.
 80340171A – Gr. 6L – 10N48L – 9,5mm.
 80340172A – Gr. 7L – 10N47L – 11,0mm.

Isolator:



80300189A

svejse madsen

Bjarne Risbjerg Madsen ApS

☎ 98 23 14 36

Oversigtsliste.: 50141063OS

Sliddele TIG 201 SR17

Gaslinse dele



Isolator:



80300189A

Isolator for gaslinse lille:



80300188A

Isolator for gaslinse stor:



80300220A

Spændbøsning:



80330100B – 1,0mm

80330101B – 1,6mm

80330102B – 2,4mm

80330103B – 3,2mm

80330104B – 4,0mm

Spændbøsning SKRÅ:



80330101BS – 1,6mm

80330102BS – 2,4mm

80330103BS – 3,2mm

Keramisk gasdyse for gaslinse:



80340400B – 6,4mm - gr.4

80340401B – 8,0mm - gr.5

80340402B – 9,8mm - gr.6

80340403B – 11,2mm – gr.7

80340404B – 12,7mm – gr.8

80340406B – 15,7mm – gr.12

Keramisk gasdyse:



80344401A – GL Gr.5L 54N17L

80344402A – GL Gr.6L 54N16L

80344403A – GL Gr.7L 54N15L

Gaslinse:



80310411B – 1,0mm

80310412B – 1,6mm

80310413B – 2,4mm

80310414B – 3,2mm

80310415B – 4,0mm

svejse madsen

Bjarne Risbjerg Madsen ApS

☎ 98 23 14 36

Oversigtsliste.: 50141063OS

Sliddele TIG 201 SR17

STUBBY dele



Stubby elektrodeholder:



80310020A – 1,0-3,2

Stubby isolator:



80300236A

Stubby gaslinse:



80310422A – 1,6mm.

80310424A – 2,4mm.

80310425A – 3,2mm.

Stubby spændb. SKRÅ:



80330031AS – 1,6mm

80330032AS – 2,4mm

80330033AS – 3,2mm

Stubby gasdyselinsse 26mm (kun til Stubby):



80440210B – nr. 4 Ø6,4

80440211B – nr. 5 Ø8,0

80440212B – nr. 6 Ø9,8

80440213B – nr. 7 Ø11,2

80440214B – nr. 8 Ø12,7

Stubby spændbøsning:



701.1221A – 1,6mm

701.1223A – 2,4mm

Gaslinse monster:



80410600A – 1,6mm

80410601A – 2,4mm

80410602A – 3,2mm

svejse madsen

Bjarne Risbjerg Madsen ApS

☎ 98 23 14 36

Oversigtsnummer: 50141063OS

Sliddele TIG 201 SR17

JUMBO dele



Jumbo spændbøsning SKRÅ:



80330101BS – 1,6mm
80330102BS – 2,4mm
80330103BS – 3,2mm

Jumbo gaslinse:



45V116 1,6mm.
45V64 2,4mm.
45V65 3,2mm.

Jumbo spændbøsning:



80330100B – 1,0mm
80330101B – 1,6mm
80330102B – 2,4mm
80330103B – 3,2mm
80330104B – 4,0mm

Jumbo keramisk:



80441327A – Gr. 8
80441328A – Gr. 12
80441329A – Gr. 10
80441330A – Gr. 16

Jumbo isolator:



54N63

svejse madsen

Bjarne Risbjerg Madsen ApS

☎ 98 23 14 36

Sliddele TIG 201 SR17

Glasklar lille



S.T. gaskop glas:



80440290A – L47mm

S.T. isolator:



80440250A

S.T. elektrodeholder:



80441245A

S.T. gaslinse lille:



80441286A – 1,0

80441287A – 1,6

80441288A – 2,4

80441289A – 3,2

80441290A – 4,0

Spændbøsning SKRÅ:



80330101BS – 1,6mm

80330102BS – 2,4mm

80330103BS – 3,2mm

Spændbøsning:



80330100B – 1,0mm

80330101B – 1,6mm

80330102B – 2,4mm

80330103B – 3,2mm

80330104B – 4,0mm

S.T. Gasdyse:



80440256A – nr. 4

80440257A – nr. 5

80440258A – nr. 6

80440259A – nr. 7

80440260A – nr. 8

svejse madsen

Bjarne Risbjerg Madsen ApS

☎ 98 23 14 36

Sliddele TIG 201 SR17

Glasklar stor



S.T. gaskop glasklar stor:



80440291A

S.T. elektrodeholder stor:



80440255A

S.T. isolator:



80440251A

S.T. gaslinse stor:



80440270A – 1,0

80440271A – 1,6

80440272A – 2,4

80440273A – 3,2

S.T. spændbøsning skrå:



80441250A – 1,0

80441251A – 1,6

80441252A – 2,4

80441253A – 3,2

80441254A – 4,0

S.T. Gaskop Stor keramisk:



80440291AK

Sliddele til TIG 201 SR17

Kemppi Glasdyse

Glasdyse lige:



SP015847 – Ø14,8 L32,5

Glasdyse:



SP015848 – Ø20,2 L32,5

Glasdyse filter:



SP015851

Glasdyse O-ring:



SP009746

Stubby elektrodeholder:



80310020A – 1,0-3,2

Stubby isolator:



80300236A

Stubby gaslinse:



80310422A – 1,6mm.
80310424A – 2,4mm.
80310425A – 3,2mm.

Stubby spændb. SKRÅ:



80330031AS – 1,6mm
80330032AS – 2,4mm
80330033AS – 3,2mm

Stubby gasdyselins 26mm (kun til Stubby):



80440210B – nr. 4	Ø6,4
80440211B – nr. 5	Ø8,0
80440212B – nr. 6	Ø9,8
80440213B – nr. 7	Ø11,2
80440214B – nr. 8	Ø12,7

Stubby spændbøsning:



701.1221A – 1,6mm
701.1223A – 2,4mm

svejse madsen

Bjarne Risbjerg Madsen ApS

☎ 98 23 14 36